Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	spector(s): Perkins			11-Aug-20
Company/Outport	Interme	tain Cas Campany	Unit/OPID:	8160
Company/Owner:	Internic	ountain Gas Company	Unit/OPID:	8100
Inspection Type & Time (1	day)	To	tal Inspection Days:	1
Standard: Construction:	1 Training:	(T)(D) Integrity Managem	nent: Incident:	
M/M: Follow-up: OQ: Damage Prevention: D&A:				
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
11 Aug 2020: (1.0 Construction) Observed a Das-co crew installing a new ¾" service lines at 774/758/790 Nannyberry, Kuna, Idaho. All procedures were followed. Typed up report				
Areas observed during this project were: Excavating, line locating, plastic joining, backfilling/bedding, pressure testing and EFV test.				
Attachments: IPUC Form 4 Construction Insponse of the Das-co daily Itineraries located OQ's for all observed employed	d in file for the pro	ile for the project.		
Corrective Action Required: Yes No	Fol	low-up Required:	Yes No by (date):	X
Inspector (Lead):			Date:	
Bruce Perkins	Du Eken	a second	8/11/2020	
Reviewer:	(1) who	1/4	Date:	
Darrin Ulmer	Saly 18	To	24 Aug 2	20